

**Applicable Vehicles:** Certain 2016 MY Tucson (TL) vehicles.

**Parts Information:**

Part Name	Part Number	Description	Qty
HOOD SAFETY HOOK CATCH	81150-D3010QQH		1/ KIT

**ROM ID Table**

Model Year	Cluster	Part Number	Old ROM ID (S/W Version)	New ROM ID (S/W Version)
2016	TL CLUSTER SUPERVISION (Limited w/Ultimate Pkg)	94011-D3160	1.01	1.02
			2.00	2.05
		94011-D3161	2.01, 2.02	
	TL CLUSTER STANDARD (SE, Eco, Sport, Limited w/Std Pkg)	94001-D3170 94001-D3180	9.00	9.01
			1.01	1.02
			2.00	2.05
			2.01,2.02	2.04

**GDS Information:**

Event #	Description
406	TL CLU CONTROL LOGIC IMPROVEMENT

**Warranty Information:**

Op. Code	Operation	Op. Time
61C033R0	Hood Safety Hook Catch Replacement and Cluster Upgrade	0.3 M/H

**NOTE:** Submit Claim on Campaign Claim Entry Screen